

# General Environmental Incident Summary

**Incident:** 3332      **Date/Time Notice:** 5/29/2014      1635      **DEM Incident No:**  
**Responsible Party:** Minnesota Power  
**Date Incident:** 5/29/2014      **Time Incident:** 1400      **Duration:** 5 minutes  
**County:** Oliver      **Twp:** 141      **Rng:** 87      **Sec:** 15      **Qtr:**  
**Lat:** 47.02477      **Long:** -101.69850      **Method:** Interpolation from map  
**Location Description:** An in-field construction location away from and based out of the Bison Wind Field Office which is located at 5198 30th Street, New Salem.  
**Submitted By:** William Fraundorf      **Affiliation:** Minnesota Power  
**Address:** 30 W Superior Street  
**City:** Duluth      **State:** MN      **Zip:** 55802

## Received By:

**Contact Person:** John Hollingsworth  
5198 30th Street  
New Salem, ND 58563

**Distance Nearest Occupied Building:** 1 Miles      **Release Contained:** Yes

**Type of Incident:** Spill

**Description of Released Contaminant:** Hydraulic fluid

**Volume Spilled:** 5.00 gallons

**Ag Related:** No

**EPA Extremely Hazardous Substance:** No

**Reported to NRC:** No

## Cause of Incident:

Hydraulic hose on construction equipment broke.

## Risk Evaluation:

None

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

Minimal given the spill was to soil, was immediately contained and immediately cleaned up.

## Action Taken or Planned:

Immediately contained and oily soil was dug up and containerized.

**Wastes Disposal Location:** Clean Harbors Industrial Solid Waste Landfill in Sawyer, ND

**Agencies Involved:** None

## ***Updates***

---

***Date:*** 5/29/2014    ***Status:*** Reviewed - No Action Required

***Author:*** Roberts, Kris

***Updated Volume:***

***Notes:***

Small spill of hydraulic fluid on an electrical facility site; impact was completely removed according to the report. No follow-up investigation is necessary.